



Contract No. 009359	Station Section 1 & 4A	Mile/Line: I-90 & US-12	C/S
Staked by SURVEY 7/1/2019	Date	Work Started Date 7/8/2019	Work Completed Date
Calculated by Scott Busby 8/5/2019	Date	Checked by E. Knudson 8/8/2019	Inspector Scott Busby 8/5/19

**ITEM NO. 17**  
**Section 1 - I-90, MP 33.44 to MP 136.43**  
**BEAM GUARDRAIL ANCHOR TYPE 10**

**Group Number 8**

7/30/2019 - I-90

- Station MP 85.84 LT EB - Sheet 4 - Installed **One EA** Beam Guardrail Anchor Type 10
  - 12.5 LF**
  - 3 wood post**

**ITEM NO. 17**  
**Section 4A - US-12 MP 192 to MP 203**  
**BEAM GUARDRAIL ANCHOR TYPE 10**

**Group Number: 29**

7/10/2019 - US-12

- Station MP 202.65 LT EB - Sheet 4 - Installed **One EA** Beam Guardrail Anchor Type 10
  - 12.5 LF**
  - 3 wood post**

Total: Beam Guardrail Type 31 (Section 8 & 29) = **25 LF**  
Wood Posts (Section 8 & 29) = **6 EA**  
Anchors (Section 8 & 29) = **2 EA**

**Notes:**

**How Measured: Per Each - Checked in the field as installed**

Item Num	Material Brand Name/Model Type	Manufacturer	Brand Name/Model Type	RAMS/QPL Ref. No.	Appr/Acc Code	Basis of Accept
017.03	Beam Guardrail Wood Post and Blocks	Superior Wood Treating		QPL-0005	2550	/ Lumber Grading Stamp or Grading Certificate and Certificate of Treatment. (If Aquatic Envir. Std. Spec. 9-09.3 (1) Applies)
						/

  

Item Num	Item Description	Grp	Date Work Complete	Unit	Quantity	Ledger Entry No.	Posted By Init.	Posted By Date	Checked By Init.	Checked By Date	Est. No.
0017	BEAM GUARDRAIL ANCHOR TYPE 10	8	8/5/2019	EAC H	1	227	EK	08/09/19			5

0017	BEAM GUARDRAIL ANCHOR TYPE 10	29	8/5/2019	EAC H	1	228	EK	08/09/19			5
------	----------------------------------	----	----------	----------	---	-----	----	----------	--	--	---

**Attachments**



Things to do 82-2.xlsx  
Microsoft Excel  
Worksheet  
400 KB

DOT Form IP 422-635ER EF  
Revised 4/2009